

Test Report

Number : TWNH00062682 Date : Apr 27, 2017

Jun Lung Rubber Industries Co., Ltd. Applicant: No. 11, Gongye N. 2nd Rd., Nantou City, Nantou County 54066, Taiwan, R.O.C.

Sample Description:

Y AND ORANGE

Test Conducted:

As requested by the applicant, for details please refer to attached pages.

Conclusion:

Tested Sample	<u>Standard</u>	<u>Result</u>
Submitted Sample	UV colorfastness test	See test conducted
	 As per ASTM G154-06, cycle 1 	

Authorized by: On Behalf of Intertek Testing Services Taiwan Limited all

Matt Wang Sr. Manager

Intertek Testing Services Taiwan Ltd. 8F., No. 423, Ruiguang Rd., Neihu District, Taipei 11492, Taiwan, R.O.C. 全國公證檢驗股份有限公司 11492 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2420

Page 1 of 3



Test Conducted

Test Report

Number : TWNH00062682

UV Colorfastness Test (ASTM G154-06, Cycle):

	<u>Orange</u>	Grey
<u>After 2 Exposure Cycles / 24 hrs</u> Colour Change	4.0	4.0

Remark : Cycle 1 : 0.89 W/m²/nm @ 340 nm, 8 h UV at 60(±3)°C Black Panel Temperature; 4 h Condensation at 50(±3)°C Black Panel Temperature.

 Intertek Testing Services Taiwan Ltd.

 8F., No. 423, Ruiguang Rd., Neihu District, Taipei 11492, Taiwan, R.O.C.

 全國公證檢驗股份有限公司

 11492 台北市內湖區瑞光路 423 號 8 樓

 Tel: (+886-2) 6602-2888 · 2797-8885

Page 2 of 3



Test Report

Number : TWNH00062682



End of Report

Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: http://www.intertektwn.com/terms/. Intertek's responsibility and liability are limited to the terms and conditions of the agreement.

This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duties to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk.

Page 3 of 3

Intertek Testing Services Taiwan Ltd. 8F., No. 423, Ruiguang Rd., Neihu District, Taipei 11492, Taiwan, R.O.C. 全國公證檢驗股份有限公司 11492 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2420